


## Brass Sugar and Jam Thermometer

-  Traditional brass sugar and jam thermometer with a copper handle. Indicates temperature in 2°C increments from 40 to 200 °C. The brass casing of the thermometer measures 47 x 200mm and has a 40mm handle. The scale on the thermometer is clearly marked for caramel, crack, hard ball, soft ball, jam, and sterilise.

Specifications	Details
Range	40 to 200 Å°C
Resolution	2 Å°C
Dimensions	47 x 200mm plus a 40mm copper handle

