THERMA-HYGROMETER - COMFORT

- Displays both humidity & temperature
- Helps maintain a healthy living & work environment

These therma-hygrometers display both the humidity and temperature in addition to indicating and recording the maximum and minimum readings. Each unit features an analogue arrow indicator and a colour-coded bar to display either humidity comfort levels e.g. dry, comfort and wet (810-130) or temperature comfort levels eg. cold, comfort and hot (810-135).

These therma-hygrometers are ideal for monitoring both temperature and humidity in rooms, offices, factories and similar to ensure optimum environmental conditions are maintained.

Each unit is housed in an ABS case, measuring 20 x 100 x 110 mm, that incorporates a useful foldaway stand and a keyhole slot for hanging on a wall.

Order code	Description
810-130	Therma-hygrometer
810-135	Comfort thermometer



Specification	Temperature	Humidity	
Range	0 to 50 °C	10 to 99 %rh	
Resolution	0.1 °C/°F	1%rh	
Accuracy	±1 °C	±5 %rh (30 to 70 %rh)	
Battery & life	2 x 1.5 volt AAA - 10000 hours		
Display	Dual custom LCD)	
Dimensions	20 x 100 x 110 mm	١	
Weight	142 grams		

THERMA-HYGROMETER - ALARM

- Integral %rh & remote temperature probe
- Large LCD with max/min & alarm functions

This therma-hygrometer simultaneously displays both the humidity and temperature in addition to indicating and recording the maximum and minimum readings.

The instrument measures both humidity and temperature over the range of 0 to 49.9 °C and 20 to 99 %rh via the internal sensors. Using the external temperature sensor the temperature range is extended to -49.9 to 69.9 °C.

The unit features a temperature alert alarm that will sound when the external remote temperature probe indicates the temperature is 0 °C or below. This feature is ideal for frost/freeze alert in horticulture and similar.

The unit is housed in an ABS case, measuring 20 x 65 x 97 mm, that incorporates a useful foldaway stand and a keyhole slot for hanging on a wall.

Order code	Description
810-155	Therma-hygrometer - alarm
810-158	Replacement probe for 810-155



		\bigcirc \bigcirc
Specification	Temperature	Humidity
Range - internal	0 to 49.9 °C	20 to 99 %rh
Range - external	-49.9 to 69.9 °C	N/A
Resolution	0.1 °C/°F	1%rh
Accuracy	±1 °C	±5 %rh
Sensor type	Thermistor	Capacitance
Battery & life	1.5 volt AAA - 10000 hours	
Display	Dual custom LCD	
Dimensions	20 x 65 x 97 mm	
Weight	70 grams	

MAX/

MIN