

## PNEUMATIC CALIBRATION HAND PUMP

Generates up to 600 psi (40 bar), Comfort Grip Handles




The **Series PCHP Pneumatic Calibration Hand Pump** sources pressure and vacuum to check calibration of gages, switches, transmitters, and recorders. The contoured cushion handles provide extra comfort while preventing the pump from sliding.

## FEATURES/BENEFITS

- Oversized check valve maintain smooth operation
- · Dual O-rings on pistons ensure no leaks

## **APPLICATIONS**

- · Instrument calibration
- Laboratories
- · Production areas



## **SPECIFICATIONS**

Output Ranges: -28 in Hg to 600 psi (-0.945 to 40 bar).

Process Connection: 1/4" NPT/BSP. Gage Connection: 1/8" NPT/BSP.

Materials: SS fittings, anodized aluminum housing, plastic/rubber handles, and

nitrile O-rings.

Weight: 2 lb (0.91 kg).

MODEL CHART		
Model	Description	
PCHP-1	Pneumatic calibration hand pump	
PCHP-1K	Pneumatic calibration hand pump with hose kit	

ACCESSORIES		
Model	Description	
PCHP-HK	High pressure hose	